Images from

The "Lettering Cutting with the Pneumatic Tool" section

from *The Manual of Monumental Lettering*, published by Monumental News, early 1900s, pp. 5-35 available on Stone Quarries and Beyond at

http://quarriesandbeyond.org/cemeteries_and_monumental_art/pdf/manual_of_monumental_lettering-pub_by_monumental_news_chicago-1920s.pdf

This section, which begins on the next page, is presented on the Stone Quarries and Beyond web site.

http://quarriesandbeyond.org/

Peggy B. Perazzo
Email: pbperazzo@comcast.net
June 2015




Fig. 1. Laying off letter with T square and T Rule

Fig. 2. Position of tool to check over pencil lines




Fig. 4. Position of tool to start a V

Fig 5. Position of lettering block and tool to chip a straight line




Fig. 3. Showing position of tool and direction in which to cut sunken bar




Fig. 4. Position of tool to start a V

Fig. 5. Position of lettering block and tool to chip a straight line




Fig. 6. Position of chisel when starting to clean a straight bar





Fig. 7. How to hold chisel to clean a round sunken letter






Fig. 9. (a) Narrow; (b) Rougher

Fig. 10. Heavy lines show start; dotted lines finish of cut




Fig. 12. Cutting inside of a letter square down with a narrow chisel

Fig. 11. Arrows show direction to cut, proceed away from cut corner




Fig. 13. A Cleaner




Fig. 14. Cutting V-shaped ridge for raised letters Fig. 15. How the finished letter looks




Fig 16. How to lay off round raised letters




Fig. 17.
CENTER LINES DRAWN
TO KEEP SIZE
AND FORM.



Fig. 20.

CONNECTING BARS

WITH SHARP

LINES.




Fig. 18.

POSITION OF CHISEL
TO CLEAN ROUND
RAISED LETTER.




Fig. 19.
FINISHING HEAD OF
ROUND RAISED
LETTER.

Fig. 17. Center lines drawn to keep size and form

Fig. 18. Position of chisel to clean round raised letter

Fig. 19. Finishing head of round raised letter

Fig. 20. Connecting bars with sharp lines




Fig. 20A. & Fig. 20B.




Fig. 21. The head higher than the main bar




Fig. 22. How to chip the outside round

Fig. 23. Position of chisel to cut inside square down




Fig. 25. Pointing under the cut line, perpendicular with the checked line Fig. 24. Position of chisel cutting away from checked line




Fig. 26. Top line shows how near to cut to finish line before using mallet to clean Fig. 27 Showing how to scratch lines on marble




Fig. 28. How to take the rough away with a plain chisel.




Fig. 29. How to start and finish a side cut square down Fig. 31. How to hold chisel to clean marble tracing




Fig. 30. Showing the proper position to hold and use a frosting tool




Fig. 32. Roughing out a straight bar for marble sunken letter




Fig. 34. How to finish a side square down

Fig. 33. Position of chisel to cut the side straighter




Fig. 35. Position of tool to rough out a round bar v-shape